BRANSON

Ultrasonic Welding



Acoustic Interface Washers

The operating efficiency of ultrasonic equipment will be greatly affected if the mating interfaces of the converter/ booster/ horn stack are not flat, make poor contact with each other, or become corroded. Branson has found that using acoustic interface washers at the interfaces between the converter and booster, and the booster and horn (instead of silicone grease) will minimize this corrosion. Poor contact can cause these unwanted conditions:

- Higher power draw in air and under load.
- High pitched noise.
- Tuning may be difficult or impossible.
- Weld quality may be affected.
- Converter may be heat damaged.



Fretting corrosion on horn/ booster interface

These conditions will be magnified if the equipment is run in continuous operation. Fretting corrosion (which looks like black surface oxidation) is the most common issue affecting frequencies from 15 to 30 kHz. This corrosion is caused by friction being generated at the interfaces between the converter and booster and the booster and horn. Note: Typically, 40 kHz does not generate enough amplitude to create fretting corrosion. For this frequency, the standard Branson silicone grease (Dow Corning #111) should be utilized.



Ultrasonic Welding

Before using the washers, follow the steps outlined in Branson TechnoLog TL-3 to recondition the converter/booster/ horn interfaces. Important: Do not use both silicone and an acoustic interface washer. Use only one washer per interface.

It is advisable with new ultrasonic installations to monitor the converter/booster/horn stack to determine when the washer should be replaced. A typical installation will run six to twelve months before requiring a washer change.

The "life expectancy" of an acoustic interface washer will be determined by the following factors:

- Booster ratio: higher amplitude = shorter life.
- Duty cycle: 50% or higher
 = shorter life.
- Quality of contact surface before washer is used.

ORDERING INFORMATION

Branson EDP No.
100-063-652
100-063-713
100-063-472
100-063-471
100-063-357
100-063-632
100-063-712

BRANSON

Branson Ultrasonics Corporation 41 Eagle Road, Danbury, CT 06813-1961 (203) 796-0400 • Fax: (203) 796-9838 www.bransonultrasonics.com e-mail: info@bransonultrasonics.com

475 Quaker Meeting House Rd., Honeoye Falls, NY 14472 (585) 624-8000 • Fax: (585) 624-1262